


Accuracy - How close measurements
to actual

Precision - How close together
a group of measurements
are to each



Resolution - 2.1
2.75
small increment that
can be measured



Accuracy - How close a measurement is to the actual value



Precision - How close a group of measurements are to each other

Resolution - smallest increment able to be measurement